



Technical Circular

No.: 123/2017

Date: 06th October 2017

To whomsoever it may concern

Subject: Panama Circular reg. Correction of Deficiencies found in ASI Inspections.

- Panama maritime authority has revised circular MMC-201 regarding correction of deficiencies raised during annual safety inspection (ASI) on vessel.
- Master, DPA, Owner/operator are required to report the correction of deficiencies raised during annual safety inspection; within 30 days of inspection to Flag State Section at marsegur@amp.gob.pa.
- Procedure of reporting to flag state is to be included in vessel's ISM manual and review of same to be carried out during initial, intermediate, renewal and additional verification of SMC audit.
- In case of deficiency not duly closed by administration or corrections of deficiency have not been provided to flag state within 30 days; a finding is to be recorded in audit report.
- The correction of the deficiencies shall be sent using the format 'Monitoring and Correction of Deficiencies Reports' [Form (F-IASI-01-01)].
- Below are the contact details of Administration's "Flag State Section"
Phone: (507) 501-5089 / 501-5084 / 501-5034 / 501-5033
Fax: (507) 501-5035
Email: marsegur@amp.gob.pa / asi@amp.gob.pa
- Ship owners / operators and masters are advised to be guided by above.

Enclosure:

1. Panama Maritime Authority Merchant Marine Circular MMC-201.

Whilst the utmost care has been taken in the compilation of the Technical Information, neither Indian Register of Shipping, its affiliates and subsidiaries if any, nor any of its directors, officers, employees or agents assume any responsibility and shall not be liable to any person for any loss, damage or expense caused in any manner whatsoever by reliance on the information in this document.